A member of The Marmon Group of companies

## INTERNAL MEMORANDUM

SHOW NAME, TITLE AND UNIT OF ADDRESSEE AND ADDRESSOR

CC: R. Brown

D. Cornell

OTHER ADDRESSEES . FOR INFORMATION

J. Sundstrom 1538

P. Tandler File

1104

10: Bob Conreaux

HQ-10

DATE: December 31, 1981

FROM: John Schuster

SUBJECT: Sludge Determinations

Sludge determinations were made on samples of well water, city water, iron tank effluent and on samples of iron tank effluent mixed with well water and with city water in a 95:5 ratio (95 parts water and 5 parts iron tank effluent).

These samples were collected on 28 December 1981.

Sample	<u>pH</u>	Sludge, gpl	Sludge p/1000 gal
Well Water	7.8	0.8780	7•33
City Water	7.9	0.0400	0.33
Iron Tank	2.4	1.9150	1 <b>5.</b> 98
Well & Iron Tank	6.9	0.7710	6.43
City & Iron Tank	6.4	0.1610	1.34

Laboratory Director

13/23/51

#### CERRO COPPER PRODUCTS CO.

A member of The Marmon Group of companies

## INTERNAL MEMORANDUM

SHOW NAME, TITLE AND UNIT OF ADDRESSEE AND ADDRESSOR

CC: R. Brown

D. Cornell

J. Sundstrom

P. Tandler

File

1104

10: Bob Conreaux

DATE: December 23, 1981

ili: Dob Confeaux

FROM:

John Schuster

SUBJECT:

HQ-10

Sludge Determinations

Sludge determinations were made of samples of well water, city water, iron tank effluent, and samples of iron tank effluent mixed with well water and with city water in a 95:5 ration (95 parts water and 5 parts iron tank effluent). These samples were collected on 21 December 1981.

<u>Sample</u>	рН	Sludge, gpl	Sludge,p/1000 gal
Well Water	7.9	0.5980	4.99
City Water	7.8	0.0490	0.41
Iron Tank	3.6	6.2390	52.06
Well & Iron Tank	6.3	1.2300	10.26
City & Iron Tank	6.2	0.2360	1.97

Laboratory Director

A member of The Marmon Group of companies

INTERNAL MEMORANDUM

SHOW NAME, TITLE AND UNIT OF ADDRESSEE AND ADDRESSOR

R. Brown

D. Cornell

J. Sundstrom

A. Tandler File

OTHER ADDRESSEES . FOR INFORMATION

10 Bob Conreaux

HQ-10

December 22, 1981 DATE: \_\_

FROM: John Schuster

SUBJECT: Sludge Determinations

Sludge determinations were made on samples of well water, city water, iron tank effluent, and samples of iron tank effluent mixed with well water and with city water in a 95:5 ratio (95 parts water and 5 parts iron tank effluent). These samples were collected on 14 December 1981.

Sample	<u>pH</u>	Sludge, gpl	Sludge, p/1000 gal
Well Water	7.8	0.6160	5.14
City Water	7.6	0.0400	0.33
Iron Tank	2.5	53.41	445.71
Well & Iron Tank	5.9	1.9690	16.43
City & Iron Tank	3.6	1.1040	9.21

#### CERRO COPPER PRODUCTS CO.

A member of The Marmon Group of companies

## INTERNAL MEMORANDUM

SHOW NAME, TITLE AND UNIT OF ADDRESSEE AND ADDRESSOR

CC: R. Brown

D. Cornell

J. Sundstrom

P. Tandler

File

1104

10: Bob Conreaux

HQ-10

Date: December 10, 1981

FROM: John Schuster

SUBJECT: Sludge Determinations

Sludge determinations were made on samples of well water, city water, iron tank effluent, and samples of iron tank effluent mixed with well water and with city water in a 95:5 ratio (95 parts water and 5 part iron tank effluent).

Sample	рН	Sludge, gpl	Sludge, p/1000 gal
Well Water	6.3	1.5030	12. <i>5</i> +
City Water	7.6	0.0710	0 <b>.</b> 59
Iron Tank	3.5	7.9400	66.26
Well & Iron Tank	6.4	1.0530	8.79
City & Iron Tank	5.7	0.2410	2.01

Laboratory Director

CERRO COPPER PRODUCTS CO.

A member of The Marmon Group of companies

# INTERNAL MEMORANDUM

SHOW NAME, TITLE AND UNIT OF ADDRESSEE AND ADDRESSOR

CC: P. Tandler File

DATE: December 1, 1981

FROM: John Schuster

SUBJECT: Well Water Analysis

Dave Cornell

The sample of well water submitted was analyzed with the following results:

pH	6.0
Suspended Solids	150 ppm
Total Dissolved Solids	1100 ppm
Residue @ 103°C	1800 ppm
Fe	87 ppm
Cu	Nil
Ni	70 ppm
Zn	5 ppm
Pb	Nil
Ca	444 ppm
Mg	115 ppm
Chlorides	45 ppm
Sulfates	2000 ppm

Laboratory Director

1104 ca P.T. 7/13/8/ File W.T.P. From

7/13/81

CARL MANCIONTE IN fo. on Daily Meter Realings TOTAL CE.

7/8 297,000- 305,900 131,000 7/9

4-33,000

564,000

526,200

602,900

100,000

426,200

1,701,200

ZAID.7/10 + 7/11 1,253,000 448,200

POWETER 7/17 PAT. 53,000 220,200

273,200

7/13 For. 68,000 80,700 148,700

\* Cerro East on Sepanate Powen Source & Pump: when we are down, + will not use the numbers for the aday.

WILL use day before.

7/13/8/

Rub - 7. C.

WE St. 11 have flows that we must cut off.

7/13 15 ABout normal for C.W. in Shutdown AND 7/10 is about normal for Cerio East when shotdown and the Aware CASTING Flowing east.

Jun J.

18/04/2 NI

### CERRO COPPER PRODUCTS CO.

A member of The Marmon Group of companies

# INTERNAL MEMORANDUM

SHOW NAME, TITLE AND UNIT OF ADDRESSEE AND ADDRESSOR

CC: R. E. Conreaux

R. Groves

J. Johnson

P. Tandler

File

1104

**5 7** .

HQ-10

DATE: May 26, 1981

10: Roy Brown

FROM: John Schuster

SUBJECT: Pond Residue Analysis

The three samples of filtered pond residue were analyzed and the results are given below:

Sample	Bosh Discharge	Pond Center	AP Discharge
Moisture	36.7%	57.0%	50.1%
Copper	17.3%	7.4%	10.6%
Iron	8.4%	35.1%	28.9%
Lead	2.4%	1.8%	5 <b>.3</b> %
Silver	.003%	.003%	.007%
Zinc	2.8%	2.9%	1.77%
Tin	7.0%	4.6%	7.1%
Sample Date	16 April 1981	18 May 1981	18 May 1981

Laboratory Director

CERRO COPPER PRODUCTS CO.

A member of The Marmon Group of companies

# INTERNAL MEMORANDUM

cc: P. Tandler

R. Brown

12004

HQ-10 SHOW NAME, TITLE AND UNIT OF ADDRESSEE AND ADDRESSOR

10 John Schuster

DATE: April 6, 1981

FROM: J. Johnson

SUBJECT: Waste Treatment Sampling

Your assistance is needed in providing a short-term sampling program on our effluent from Cerro East.

It is requested that this commence on an urgent basis since the Waste Treatment Plant is now on strike. Roy Brown will furnish the daily samples for this purpose so that they can be analyzed for the parameters outlined by the Waste Treatment Plant.

Our objective in doing this is two-fold. The purpose is to determine the content of the sample. In addition, we are interested in making a comparison of this sample with previous analysis for similar flow quantity.

Our sampling techniques have been changed at Cerro East and we anticipate a change in the composite sample observed. It is expected that this condition should extend for about a thirty-day period.

JJ/jl




nun II E E

#### CERRO COPPER PRODUCTS CO.

A member of The Marmon Group of companies

P.O. Box 681 Fast St. Louis. Illinois 62202 618/337-6000





March 31, 1981

Mr. Carl Marciante Sauget Waste Treatment Plant 2897 Monsanto Avenue Sauget, Illinois 62206

Dear Mr. Marciante:

The sampling system as outlined on the Consoer, Townsend and Associates drawing Project No. 78223, no date, has been installed with minor modifications on the Cerro East Lift Station.

In the past, your representative has collected two samples from the old catch bottle, retaining one for your analysis and dropping off one at our laboratory. After collecting samples, he has emptied the collection bottle and replaced for the next day's collection.

We ask that he continue this procedure, except collect his samples from the sample station drum (freeze protected), distribute one to you and one to our lab, the only difference being that he should open the cock valve drain on the 55-gallon drum each day, thereby draining the previous day's collection. Then reclose for the accumulation of the new sample. Costs for this installation have been incurred by Cerro.

Should you have any questions, please advise.

Yours very truly,

CERRO COPPER PRODUCTS CO. A Member of The Marmon Group

James C. Johnson

Manager of Engineering

JCJ/jpl

cc: J. Dalton (S.W.T.P.)

7. Tandler

R. Brown

TO: J. Johnson

To: J. Johnson

Trom P & Connear

From P & Connear

From P & Connear

From P & Connear

File-Rec

Subject: Emergency Plan - Waste Wate Treatment

I will notify the appropriate production Supervision. If I am not available call the four General Foremen from many Department.

Please change the curtailment plan for Building 19 as morked so that maint cuts of the water to the A.P. settleing Tank (not the make up as indicated) and months the 3 cooling tower. The Maint Plant normally does all the adjusting & knows which values are which etc. The "costing pit water in Blog 19 is what? I can only think of the sump in the pit. Surely you don't mean the cooling water for the molds.

I am sending corpie le all Bered Forene

Pe

#### WASTE EFFLUENT CURTAILMENT PLAN

It is expected these lists will be reviewed by the department heads and assigned to specific individuals in their departments for action and accountability in the event of a request of shutdown of our effluent.

Production departments are requested to designate singular contacts in each area for communication purposes and follow up of our effectiveness.

LOCATION	l	A . 1 *	Danaanihiliha
Source	<u>  Item</u>	Action	Responsibility
METAL RECEIVING Sample Room	<u>G</u>	Shut Off	Maintenance
Hoses	•	Cut Off	Production
BUILDING 19			
A. P. System	Valve – Make up	Monitor NA N	Production
Three Cooling		v Monitor	Production
Casting Pit Wo	Pump John S	Shut Down	Maintenance
Compressor Co Tower	poling Pump Jatur Costing The Pumps	Check for Overflow	Maintenance
Locker Room	Showers, Drinking Fountain, Urinals	Cut Off All Running Water	Area Product Supervisor
Hoses		Shut Off	Production
ANODE OPERATION	ON	÷	
Casting	Wheel & Bosh Tank	Stop Costing and Cut Off Water	Production
6 Deep Well	,	Shut Down After Wheel is Empty	Maintenance
Hydraulic Oil	Coolers	Shut Down	Maintenanc
3 A. P. Syst	em Recycle & Quench Tank	Stop All Overflow	Maintenanc
A. P. Fan Oi	l Coolers	Shut Down	Maintenanc

A. P. Fan Blades

Shut Down

Maintenanc